



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

January 31, 2006

Supervisor DRH

Mine Name: Lynn Springs

Operator Name: Bonneville Quarries, Inc
(Bill Bown)

Inspector(s): Lynn Kunzler, DOGM

Other Participants: none

Mine Status: Active

Permit number: M/003/025

Inspection Date: November 02, 2005

Time: 11:30 am

Weather:

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This inspection was done to document site conditions while in the area

Inspection Summary:

One goal of this inspection trip was to have Mr. Bown sign the transfer documents for the Green Beetle permit (S/003/017). This site was one of 3 sites that it was reported by others that Mr. Bown may be located. The site had been active recently as determined by the fresh disturbances. There was trackhoe on site. However, no one was at this site.

Conclusions and Recommendations:

This site appeared to be in compliance at this time - continue to monitor this site when in the area.

Inspector's Signature 495

Date: January 31, 2006

LK:pb

O:\M003-BoxElder\M0030025-Lynnsprings\inspections\insp-11022005.doc